



July 26, 2016

Mr. Mark Pruchnicki  
Maintenance Director  
Cuyahoga Valley Career Center  
8001 Brecksville Road  
Brecksville, OH 44141

**Subject: AHERA Three-Year Re-Inspection of the Cuyahoga Valley Career Center**

Dear Mr. Pruchnicki,

Lawhon and Associates, Inc. (L&A) is pleased to submit the attached report for the AHERA Three Year Re-Inspection of the Cuyahoga Valley Career Center. The scope of this project was to reassess the condition and friability of confirmed and assumed asbestos-containing building material throughout three facilities following AHERA regulations.

Mr. Jordan Mederer of L&A conducted the re-inspection July 18, 2016. Mr. Mederer is licensed by the Ohio Department of Health as an Asbestos Hazard Evaluation Specialist (# 35005).

Thank you for utilizing L&A to conduct this project. If we can answer any questions or be of any assistance, please contact Jordan Mederer or Chuck Wilson at (614) 481-8600.

Sincerely,

Jordan Mederer, AHES 35005  
HBM Department Manager

Chuck Wilson  
Vice President

## ***AHERA 3-YEAR RE-INSPECTION:***

---

***Cuyahoga Valley Career Center  
8001 Brecksville Road  
Brecksville, Ohio 44141  
(L&A Project 16-0288)***



***Prepared for:***

***Mr. Mark Pruchnicki  
Maintenance Director  
Cuyahoga Valley Career Center  
8001 Brecksville Road  
Brecksville, Ohio 44141***

***Prepared by:***

***Lawhon & Associates, Inc.  
1441 King Avenue  
Columbus, Ohio 43212***

***July 26, 2016***



## Table of Contents

Summary

Inspection Report .....	1
Inspector Certifications .....	Section 1
Homogeneous Area List.....	Section 2
Room Inventory .....	Section 3
Assessment Sheets .....	Section 4

The AHERA 3-year Re-Inspection of:

**Cuyahoga Valley Career Center  
8001 Brecksville Road  
Brecksville, Ohio 44141**

revealed the presence of:

Non-Friable Asbestos Materials  
Friable Asbestos Materials

## **Inspection Report**

On July 18, 2016, Mr. Jordan Mederer (Certified Asbestos Hazard Evaluation Specialist #35005) of Lawhon & Associates, Inc. (L&A) performed a re-inspection of the previously described school.

The inspection was conducted in accordance with the guidelines set forth in the Asbestos Hazard Emergency Response Act (AHERA) and as stated in 40 CFR Part 763, Asbestos-Containing Materials in Schools; Final Rule and Notice as published in the October 30, 1987 Federal Register.

Specifically, the re-inspection consisted of a visual inspection and assessment of condition of all known or assumed, asbestos containing building materials (ACBM). Each material was touched to determine its friability. Additionally an assessment of the asbestos-containing material's condition, and its potential for damage and/or disturbance was made.

The inspector, Mr. Jordan Mederer is certified by the Ohio Department of Health as an Asbestos Hazard Evaluation Specialist. The inspector has successfully completed the 40-hour Building Inspector/Management Planner course and an annual refresher course each year since initial certification. Copies of the inspector's current certificates are included in Section 1.

Suspected asbestos-containing materials have been grouped into "Homogeneous Areas." Materials of the same type which are similar in color, texture, and date of application were grouped together in Homogeneous Areas. Each material is also further classified into one of the three following groups: 1) Surfacing - materials which are spray or trowel applied, 2) Thermal - materials whose primary purpose in the retention or isolation of heat, and 3) Miscellaneous - materials which do not fit into the previous two categories.

Materials that can be crumbled or reduced to a powder by hand pressure when dry are considered to be "friable," those that can not are considered to be "non-friable." Typical friable materials include ceiling tiles, spray-on fire proofing, and thermal insulation. Typical non-friable materials include floor tile, intact hard plaster, and transite.

The condition of each asbestos material has been rated and placed into one of the following five categories:

- 1) No damage,
- 2) 0-10% Distributed damage,
- 3) >10% Distributed significant damage,
- 4) 0-25% Localized damage, and

- 5) >25% Localized significant damage.

The potential for future damage to each asbestos material has also been rated and placed into one of the following three categories:

- 1) Low potential for future damage,
- 2) Moderate potential for future damage, and
- 3) Significant potential for future damage.

The condition and potential for damage of each material were reviewed and response actions were recommended. Recommended response actions fall into one of the following categories:

- 1) Repair - properly trained, equipped and accredited personnel should repair the damaged materials.
- 2) Operations and Maintenance - the District's Operations and Maintenance plan should remain in effect, to prevent disturbance to the material. This plan includes such items as staff, contractor and occupant notifications, and periodic inspections.
- 3) Isolate/Abate - The material has suffered significant damage in the past and presents an immediate health hazard. The area should be isolated until the hazard can be abated.

Section 2 contains a listing of each Homogeneous Area along with an indication of the material type, an indication of the friability of the material, the current condition of the material, the current potential for damage of the material and recommended response actions.

Section 3 contains a listing of Room/Area Inventory, which indicates the quantity and locations of asbestos containing materials.

Section 4 contains an Assessment Sheet for each homogeneous area that contains asbestos, or is assumed to contain asbestos.

## Summary

On July 18, 2016, L&A conducted a reinspection of Cuyahoga Valley Career Center as required under AHERA 40 CFR Part 763.

Building materials, which contain or are assumed to contain asbestos in the school, includes floor tile and associated mastic, thermal pipe fitting insulation, ceiling panels, drywall/joint compound, black sink undercoating, lab table tops, linoleum, stucco wall plaster, and vibration dampeners (flexible duct connectors).

L&A recommends all materials remain in the operations and maintenance plan. Period inspection should take place every 6 months. Any disturbance or change of condition of these materials should be immediately handled by a trained person. Damaged ceiling tiles should be replaced.



---

Jordan Mederer  
Ohio Asbestos Hazard Evaluation Specialist #35005

**Section 1**  
**Inspector Certifications**



# The InService Training Network

## Asbestos Building Inspector and Management Planner Refresher Courses



**Jordan Mederer**

has successfully completed the Asbestos Building Inspector and Management Planner Refresher Courses and passed by at least 70% the course examinations for accreditation under Section 206 of the Toxic Substance Control Act, Title II, and Indiana 326 IAC 18-2 Provided by: The InService Training Network, Inc., 6813 Flags Center, Columbus, OH 43229 (614) 895-9323

**Course Dates:** July 6, 2016

**Course Director:**

*Kurt Varga*  
Kurt Varga

**Expiration Date:** July 6, 2017

**Examination Date:** July 6, 2016

**Course Location:** Columbus, Ohio

**Certificate Numbers:** ITNIR-5920 & ITNMPR-5920



# OHIO DEPARTMENT OF HEALTH

246 North High Street  
Columbus, Ohio 43215

614/466-3543  
www.odh.ohio.gov

John R. Kasich/Governor

Richard Hodges/Director of Health

August 11, 2015

Jordan R Mederer  
Lawhon & Associates, Inc  
1441 King Avenue  
Columbus OH 43212

RE: Asbestos Hazard Evaluation Specialist  
Certification Number: ES35005  
Expiration Date: 08/08/2016

Dear Jordan R Mederer:

This letter and enclosed certification card approves your request to be certified as an Asbestos Hazard Evaluation Specialist. You must present your card upon request at any project site while performing duties. Copies of cards are not acceptable as proof of certification.

This certification may be revoked by the Director of Health for violation of any of the requirements of 3701-34 of the Ohio Administrative Code.

If you have any questions, please call Kathy Butcher, Licensure Specialist, at 614-644-0226.

Sincerely,

Bill Robbins, Section Chief  
Bureau of Licensure Operations  
Office of Health Assurance and Licensing

State of Ohio  
Department of Health  
Asbestos Program

**Asbestos Hazard Evaluation Specialist**



**Jordan R Mederer**  
**Lawhon & Associates, Inc**  
**1441 King Avenue**  
**Columbus OH 43212**

Certification Number	Expiration Date
<b>ES35005</b>	<b>08/08/2016</b>

DOB: 10/23/1983

This certification is issued pursuant to Chapter 3710 of the Revised Code and 3701-34 of the Ohio Administrative Code

Certification Card is not valid if altered

## **Section 2**

### **Homogeneous Area List**

Cuyahoga Valley Career Center  
 AHERA 3-Year Re-Inspection  
 Homogeneous Area List

School Name: Cuyahoga Valley Career Center

Homogeneous Area #	Homogeneous Area Description	Material Type	Friability	Asbestos?	Current Condition	Current Potential	Recommended Response Actions
1	Fitting on dom. Hot water sys.	Thermal	Yes	Yes	No Damage	Low	O&M
1A	Fitting on dom. Cold water sys.	Thermal	Yes	Yes	No Damage	Low	O&M
1B	Fittings on cir. Hot water	Thermal	Yes	Yes	No Damage	Low	O&M
2	Transite Panels	Miscellaneous	No	Yes	Abated	N/A	N/A
3	Counter Tops	Miscellaneous	No	Assumed	No Damage	Moderate	O&M
4	9x9 floor tile and mastic	Miscellaneous	No	Assumed	No. Damage	Moderate	O&M
4A	12X12 floor tile and mastic	Miscellaneous	No	Assumed	No Damage	Moderate	O&M
5	Roof drain bowl insulation	Thermal	Yes	Assumed	No Damage	Low	O&M
6	Roof drain elbow insulation	Thermal	Yes	Assumed	No Damage	Low	O&M
7	Boiler Gasket	Thermal	Yes	No	Abated	N/A	N/A
8	Drywall Walls	Miscellaneous	No	Assumed	Minor Localized Damage	Moderate	O&M
9	Drywall Ceilings	Miscellaneous	No	Assumed	No Damage	Moderate	O&M
10	Stucco Wall Plaster	Surfacing	No	Assumed	No Damage	Moderate	O&M
11	HVAC duct insulation	Thermal	Yes	No	N/A	N/A	N/A
12	2x4 Ceiling Tile - Style 3	Miscellaneous	Yes	Assumed	Staining	Moderate	O&M
13	2x4 Ceiling Tile - Style 2	Miscellaneous	Yes	Assumed	Staining	Moderate	O&M
14	2x4 Ceiling Tile - Style 1	Miscellaneous	Yes	Assumed	Staining	Moderate	O&M
15	12x12 Ceiling Tile - Style 4	Miscellaneous	Yes	Assumed	Staining	Moderate	O&M
16	12x12 Ceiling Tile - Style 5	Miscellaneous	Yes	Assumed	Staining	Moderate	O&M
17	Vertical Hot Water Tank	Thermal	Yes	Yes	Abated	N/A	N/A
18	Carpet Squares	Miscellaneous	No	Assumed	No Damage	Low	O&M



Cuyahoga Valley Career Center  
 AHERA 3-Year Re-Inspection  
 Homogeneous Area List

School Name: Cuyahoga Valley Career Center

Homogeneous Area #	Homogeneous Area Description	Material Type	Friability	Asbestos?	Current Condition	Current Potential	Recommended Response Actions
19	Linoleum	Miscellaneous	No	Assumed	No Damage	Moderate	O&M
20	18x18 floor tile and mastic	Miscellaneous	No	Assumed	No Damage	Moderate	O&M
21	Drywall Walls (New Addition)	Miscellaneous	No	Assumed	No Damage	Low	O&M
22	N/A	N/A	N/A	N/A	N/A	N/A	N/A
23	Black Sink Insuation	Miscellaneous	No	Assumed	No Damage	Low	O&M
24	Window Glazing/ Caulking	Miscellaneous	No	Assumed	No Damage	Low	O&M
25	Vibration Dampener	Miscellaneous	No	Assumed	No Damage	Low	O&M

**Section 3**  
**Room Inventory**

Cuyahoga Valley Career Center  
 AHERA 3-Year Re-Inspection  
 Room Inventory

Cuyahoga Valley Career Center

School Name:

Room	Level/ Area	Material/Description	Quantity	Asbestos?	Damaged?	Notes
Central Office Area	1	Mudded Joint Packing on Non-ACM pipe insulation	10 fittings	Yes	No	Inaccessible
Central Office Area	1	Carpet Squares	Not Quantified	Assumed	No	
Central Office Area	1	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	Staining- 7 tiles (copy room)
<b>Central Office Area</b>	<b>1</b>	<b>1 x 1 Wall Tiles</b>	<b>120 square feet</b>	<b>Assumed</b>	<b>No</b>	
Machine Tech	1	Mudded Joint Packing on Non-ACM pipe insulation	68 fittings	Yes	No	Repairs remain intact
Legal Sec. & Marketing Tech/ Career Devel.	1	Mudded Joint Packing on Non-ACM pipe insulation	18 fittings	Yes	No	Inaccessible
Legal Sec. & Marketing Tech/ Career Devel.	1	Carpet Squares	Not Quantified	Assumed	No	
Legal Sec. & Marketing Tech/ Career Devel.	1	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	Staining- 1 tile (legal sec.)
CAD	1	Mudded Joint Packing on Non-ACM pipe insulation	25 fittings	Yes	No	Inaccessible
CAD	1	Carpet Squares	Not Quantified	Assumed	No	
CAD	1	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	
CAD	1	Drywall Walls	Not Quantified	Assumed	No	
Staff Lounge	2	Carpet Squares	400 square feet	Assumed	No	
Staff Lounge	2	2 x 4 Ceiling Tiles	400 square feet	Assumed	No	
Staff Lounge	2	1 x 1 Ceiling Tiles	40 square feet	Assumed	No	
Staff Lounge	2	Black Sink Insulation	1 sink	Assumed	No	

**Bold** denotes changes from last inspection conducted April 1, 2013.

Cuyahoga Valley Career Center  
 AHERA 3-Year Re-Inspection  
 Room Inventory

Room	Level/ Area	Material/Description	Quantity	Asbestos?	Damaged?	Notes
<b>Records Room Above Staff Lounge</b>	<b>2</b>	<b>Mudded Joint Packing on Non-ACM pipe insulation</b>	<b>18 fittings</b>	<b>Yes</b>	<b>No</b>	
Media Tech, Heating & Air Area	2	Mudded Joint Packing on Non-ACM pipe insulation	100 fittings	Yes	No	
Media Tech, Heating & Air Area	2	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	
Media Tech, Heating & Air Area	2	Carpet Squares	Not Quantified	Assumed	No	
Media Tech, Heating & Air Area	2	Drywall Walls/ Soffit	Not Quantified	Assumed	No	
<b>Compressor Room</b>	<b>2</b>	<b>Mudded Joint Packing on Non-ACM pipe insulation</b>	<b>9 fittings</b>	<b>Yes</b>	<b>No</b>	<b>5 tiles damaged (broken/staining)</b>
<b>Compressor Room</b>	<b>2</b>	<b>2 x 4 Ceiling Tiles</b>	<b>Not Quantified</b>	<b>Assumed</b>	<b>Yes</b>	
C.N.A., Voc Eval, Elec. Eng., Spec. Ed.	2	Mudded Joint Packing on Non-ACM pipe insulation	20 fittings	Yes	No	
C.N.A., Voc Eval, Elec. Eng., Spec. Ed.	2	9 x 9 Floor Tile and Mastic	<b>1,300 square feet</b>	Assumed	No	<b>Partially covered with carpet, exposed in storage rooms</b>
C.N.A., Voc Eval, Elec. Eng., Spec. Ed.	2	12 x 12 Floor Tile and Mastic	Not Quantified	Assumed	No	
C.N.A., Voc Eval, Elec. Eng., Spec. Ed.	2	Carpet Squares	Not Quantified	Assumed	No	<b>over 9" floor tile?</b>
C.N.A., Voc Eval, Elec. Eng., Spec. Ed.	2	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	
Digital Design & Graphic Imaging Area	2	Mudded Joint Packing on Non-ACM pipe insulation	28 fittings	Yes	Yes	<b>Repairs remain intact</b>
Digital Design & Graphic Imaging Area	2	9 x 9 Floor Tile and Mastic	460 square feet	Assumed	No	<b>no longer visible (enclosed under carpet or 12" tile)</b>
Digital Design & Graphic Imaging Area	2	12 x 12 Floor Tile and Mastic	Not Quantified	Assumed	<b>Yes</b>	<b>paint/ chemical rooms- significant staining (400 sf)</b>

**Bold** denotes changes from last inspection conducted April 1, 2013.



Cuyahoga Valley Career Center  
 AHERA 3-Year Re-Inspection  
 Room Inventory

Room	Level/ Area	Material/Description	Quantity	Asbestos?	Damaged?	Notes
Digital Design & Graphic Imaging Area	2	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	
Digital Design & Graphic Imaging Area	2	Carpet Squares	Not Quantified	Assumed	No	
Mechanical 309	3	Mudded Joint Packing on Non-ACM pipe insulation	18 fittings	Yes	No	
Public Health and Safety & Science Lab	3	Mudded Joint Packing on Non-ACM pipe insulation	26 fittings	Yes	No	<b>Inaccessible no longer visible (enclosed under carpet?)</b>
Public Health and Safety & Science Lab	3	9 x 9 Floor Tile and Mastic	120 square feet	Assumed	No	
Public Health and Safety & Science Lab	3	12 x 12 Floor Tile and Mastic	2,400 square feet	Assumed	No	
Public Health and Safety & Science Lab	3	Carpet Squares	Not Quantified	Assumed	No	
Public Health and Safety & Science Lab	3	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	
Public Health and Safety & Science Lab	3	Drywall Walls	Not Quantified	Assumed	Minor	<b>Loc damage in 312A (corner guard, small hole; &lt;1sf)</b>
Science Lab	3	Table Tops	210 square feet	Assumed	No	
Science Lab	3	Linoleum	1460 square feet	Assumed	No	
Science Lab	3	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	
Health/Dental	3	12 x 12 Floor Tile and Mastic	800 square feet	Assumed	No	
Health/Dental	3	Table Tops	210 square feet	Assumed	No	
Health/Dental	3	Carpet Squares	Not Quantified	Assumed	No	
Health/Dental	3	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	
Health/Dental	3	Drywall Walls	Not Quantified	Assumed	No	

**Bold** denotes changes from last inspection conducted April 1, 2013.

Cuyahoga Valley Career Center  
 AHERA 3-Year Re-Inspection  
 Room Inventory

Room	Level/ Area	Material/Description	Quantity	Asbestos?	Damaged?	Notes
Health/Dental	3	Black Sink Insulation	2 sinks	Assumed	No	
Health/Dental	3	9 x 9 Floor Tile and Mastic	120 square feet	Assumed	No	
Health/Dental	3	1 x 1 Ceiling Tiles	40 square feet	Assumed	No	
Auto Mech	3	Mudded Joint Packing on Non-ACM pipe insulation	63 fittings	Yes	No	
Auto Mech	3	Carpet Squares	Not Quantified	Assumed	No	
Auto Mech	3	2 x 4 Ceiling Tiles	80 square feet	Assumed	<b>Yes</b>	<b>2 damaged tiles in classroom</b>
Auto Mech	3	Table Tops	Not Quantified	Assumed	No	
Maintenance Area & Central Supply	4	Mudded Joint Packing on Non-ACM pipe insulation	<b>18 fittings</b>	Yes	No	Fittings are intact
Maintenance Area & Central Supply	4	Transite Panels	<b>Abated</b>	Yes	<b>N/A</b>	<b>Material not identified and assumed to be abated</b>
<b>Maintenance Area &amp; Central Supply</b>	<b>4</b>	<b>Drywall Ceiling</b>	<b>200 square feet</b>	<b>Assumed</b>	<b>No</b>	
<b>Maintenance Area &amp; Central Supply</b>	<b>4</b>	<b>2 x 4 Ceiling Tiles</b>	<b>100 square feet</b>	<b>Assumed</b>	<b>No</b>	
S&S/ Trans to Work, Voc. Adj. Lab, HS, Conference Rm A	4	Mudded Joint Packing on Non-ACM pipe insulation	21 fittings	Yes	No	<b>Inaccessible</b>
S&S/ Trans to Work, Voc. Adj. Lab, HS, Conference Rm A	4	9 x 9 Floor Tile and Mastic	<b>80 square feet</b>	Assumed	No	
S&S/ Trans to Work, Voc. Adj. Lab, HS, Conference Rm A	4	12 x 12 Floor Tile and Mastic	120 square feet	Assumed	No	

**Bold** denotes changes from last inspection conducted April 1, 2013.

Cuyahoga Valley Career Center  
 AHERA 3-Year Re-Inspection  
 Room Inventory

Room	Level/ Area	Material/Description	Quantity	Asbestos?	Damaged?	Notes
S&S/ Trans to Work, Voc. Adj. Lab, HS, Conference Rm A	4	Carpet Squares	Not Quantified	Assumed	No	
S&S/ Trans to Work, Voc. Adj. Lab, HS, Conference Rm A	4	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	
S&S/ Trans to Work, Voc. Adj. Lab, HS, Conference Rm A	4	Black Sink Insulation	Not Quantified	Assumed	No	
Power Equip/ Const. Trades Area	4	Mudded Joint Packing on Non- ACM pipe insulation	69 fittings	Yes	No	Repairs remain intact
Power Equip/ Const. Trades Area	4	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	
Technology Department	5	Mudded Joint Packing on Non- ACM pipe insulation	17 fittings	Yes	No	<b>Area currently under major renovation</b>
Technology Department	5	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	<b>Area currently under major renovation</b>
Technology Department	5	Stucco Wall Plaster	Not Quantified	Assumed	No	<b>Area currently under major renovation</b>
<b>Technology Department</b>	<b>5</b>	<b>Carpet Squares</b>	<b>Not Quantified</b>	<b>Assumed</b>	<b>No</b>	<b>Area currently under major renovation</b>
<b>Technology Department</b>	<b>5</b>	<b>Drywall Walls</b>	<b>Not Quantified</b>	<b>Assumed</b>	<b>No</b>	<b>Area currently under major renovation</b>
Media Library	5	12 x 12 Floor Tile and Mastic	Not Quantified	Assumed	No	Material not visible; possibly covered by new carpet.
Media Library	5	Carpet Squares	Not Quantified	Assumed	No	
<b>Media Library</b>	<b>5</b>	<b>Roof Drain Mudded Joint Packing</b>	<b>1 each</b>	<b>Yes</b>	<b>No</b>	
Electrical & Alt Energy Systems	5	Mudded Joint Packing on Non- ACM pipe insulation	7 fittings	Yes	No	
<b>Electrical &amp; Alt Energy Systems</b>	<b>5</b>	<b>Drywall Walls</b>	<b>Not Quantified</b>	<b>Assumed</b>	<b>No</b>	

**Bold** denotes changes from last inspection conducted April 1, 2013.

Cuyahoga Valley Career Center  
 AHERA 3-Year Re-Inspection  
 Room Inventory

Room	Level/ Area	Material/Description	Quantity	Asbestos?	Damaged?	Notes
Mech/ Storage Above Elec & Alt Energy Systems	5	Mudded Joint Packing on Non-ACM pipe insulation	<b>8 fittings</b>	Yes	No	<b>Fittings are intact</b>
Mech/ Storage Above Elec & Alt Energy Systems	5	Vibration Damper	3 dampers	Assumed	No	
Mech/ Storage Above Elec & Alt Energy Systems	5	Boiler Gasket	<b>Abated</b>	<b>N/A</b>	<b>N/A</b>	Abated
Greenhouse	5	Window Glazing/ Caulking	<b>Removed</b>	<b>N/A</b>	<b>N/A</b>	<b>Greenhouse removed</b>
Main Corridor	1	Mudded Joint Packing on Non-ACM pipe insulation	7 fittings	Yes	No	
Main Corridor	2	Mudded Joint Packing on Non-ACM pipe insulation	7 fittings	Yes	No	
Main Corridor	3	Mudded Joint Packing on Non-ACM pipe insulation	6 fittings	Yes	No	
Main Corridor	4	Mudded Joint Packing on Non-ACM pipe insulation	6 fittings	Yes	No	
<b>Main Corridor</b>	<b>5</b>	<b>Mudded Joint Packing on Non-ACM pipe insulation</b>	<b>12 fittings</b>	<b>Yes</b>	<b>No</b>	
Throughout Facility	All	Carpet Squares	Not Quantified	Assumed	No	
New Cafeteria	Addition	18 x 18 Floor Tile and Mastic	Not Quantified	Assumed	No	
New Cosmetology	Addition	12 x 12 Floor Tile and Mastic	Not Quantified	Assumed	No	
New Cosmetology	Addition	Drywall Walls	Not Quantified	Assumed	No	
New Cosmetology	Addition	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	
Restaurant/ Kitchen	Addition	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	
Restaurant/ Kitchen	Addition	Drywall Walls	Not Quantified	Assumed	No	
Restaurant/ Kitchen	Addition	Carpet Squares	Not Quantified	Assumed	No	

**Bold** denotes changes from last inspection conducted April 1, 2013.

Cuyahoga Valley Career Center  
 AHERA 3-Year Re-Inspection  
 Room Inventory

Room	Level/ Area	Material/Description	Quantity	Asbestos?	Damaged?	Notes
Adult Ed./ Computer Labs	Addition	2 x 4 Ceiling Tiles	Not Quantified	Assumed	No	
Adult Ed./ Computer Labs	Addition	Drywall Walls	Not Quantified	Assumed	No	
Adult Ed./ Computer Labs	Addition	Carpet Squares	Not Quantified	Assumed	No	
<b>Health Careers/ School of Nursing (2nd Floor)</b>	<b>Addition</b>	<b>Carpet Squares</b>	<b>Not Quantified</b>	<b>Assumed</b>	<b>No</b>	
<b>Health Careers/ School of Nursing (2nd Floor)</b>	<b>Addition</b>	<b>2 x 4 Ceiling Tiles</b>	<b>Not Quantified</b>	<b>Assumed</b>	<b>No</b>	
<b>Health Careers/ School of Nursing (2nd Floor)</b>	<b>Addition</b>	<b>Drywall Walls</b>	<b>Not Quantified</b>	<b>Assumed</b>	<b>No</b>	
<b>Health Careers/ School of Nursing (2nd Floor)</b>	<b>Addition</b>	<b>18 x 18 Floor Tile and Mastic</b>	<b>Not Quantified</b>	<b>Assumed</b>	<b>No</b>	

**Bold** denotes changes from last inspection conducted April 1, 2013.

**Section 4**  
**Assessment Sheets**

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 1, 1A, 1B Description: Fitting Insulation

Material Type: Surfacing: Thermal: X Miscellaneous:

Friable?:

Yes: X

No

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	<u>X</u>	Light		Moderate		Heavy		Unknown
Water:	None	<u>X</u>	Light		Moderate		Heavy		Unknown
Physical:	None	<u>X</u>	Light		Moderate		Heavy		Unknown

**Percent Damaged:** (for inaccessible areas)


Localized:	<u>X</u>	None	0 - 25%	>25%	Unknown
Distributed:	<u>X</u>	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:	<u>X</u>	Low		Moderate		High
Vibration:	<u>X</u>	Low		Moderate		High
Air Movement:		Low	<u>X</u>	Moderate		High
Ventilation:		Low	<u>X</u>	Moderate		High
Accessibility:	<u>X</u>	Low		Moderate		High

**Overall potential rating:**

X Low Moderate High

Inspectors Signature: 

Date: 7/26/16

Inspectors Name: Jordan Mederer

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 2 Description: Transite Panels (MATERIAL ABATED)

Material Type: Surfacing Thermal Miscellaneous: X

Friable?: Yes No: X

**Type of Damage:** (for inaccessible areas)

Deterioration:	None		Light		Moderate		Heavy		Unknown	
Water:	None		Light		Moderate		Heavy		Unknown	
Physical:	None		Light		Moderate		Heavy		Unknown	

**Percent Damaged:** (for inaccessible areas)


Localized:	None	0 - 25%	>25%	Unknown
Distributed:	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:		Low		Moderate		High
Vibration:		Low		Moderate		High
Air Movement:		Low		Moderate		High
Ventilation:		Low		Moderate		High
Accessibility:		Low		Moderate		High

**Overall potential rating:**

     Low      Moderate      High

Inspectors Signature: 

Date: 7/26/16

Inspectors Name: Jordan Mederer



**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 3 Description: Counter tops

Material Type: Surfacing Thermal Miscellaneous: X

Friable?: Yes: No: X

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	X	Light		Moderate		Heavy		Unknown	
Water:	None	X	Light		Moderate		Heavy		Unknown	
Physical:	None	X	Light		Moderate		Heavy		Unknown	

**Percent Damaged:** (for inaccessible areas)


Localized:	X	None	0 - 25%	>25%	Unknown
Distributed:	X	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:		Low		Moderate	X	High
Vibration:	X	Low		Moderate		High
Air Movement:	X	Low		Moderate		High
Ventilation:	X	Low		Moderate		High
Accessibility:		Low		Moderate	X	High

**Overall potential rating:**

	Low	X	Moderate		High
--	-----	---	----------	--	------

Inspectors Signature: 

Date: 7/26/16

Inspectors Name: Jordan Mederer

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 4 Description: 9 x 9 Floor Tile and Mastic

Material Type: Surfacing Thermal Miscellaneous: X

Friable?: Yes No: X

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	<input checked="" type="checkbox"/>	Light		Moderate		Heavy		Unknown	
Water:	None	<input checked="" type="checkbox"/>	Light		Moderate		Heavy		Unknown	
Physical:	None	<input checked="" type="checkbox"/>	Light		Moderate		Heavy		Unknown	

**Percent Damaged:** (for inaccessible areas)


Localized:	<input checked="" type="checkbox"/>	None	0 - 25%	>25%	Unknown
Distributed:	<input checked="" type="checkbox"/>	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:		Low		Moderate	<input checked="" type="checkbox"/>	High
Vibration:	<input checked="" type="checkbox"/>	Low		Moderate		High
Air Movement:	<input checked="" type="checkbox"/>	Low		Moderate		High
Ventilation:	<input checked="" type="checkbox"/>	Low		Moderate		High
Accessibility:		Low		Moderate	<input checked="" type="checkbox"/>	High

**Overall potential rating:**

Low X Moderate High

Inspectors Signature: 

Date: 7/26/16

Inspectors Name: Jordan Mederer

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 4A Description: 12 x 12 Floor Tile and Mastic

Material Type: Surfacing Thermal Miscellaneous: X

Friable?: Yes No: X

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	<input checked="" type="checkbox"/>	Light		Moderate		Heavy		Unknown	
Water:	None	<input checked="" type="checkbox"/>	Light		Moderate		Heavy		Unknown	
Physical:	None	<input checked="" type="checkbox"/>	Light		Moderate		Heavy		Unknown	

**Percent Damaged:** (for inaccessible areas)


Localized:	<input checked="" type="checkbox"/>	None	0 - 25%	>25%	Unknown
Distributed:	<input checked="" type="checkbox"/>	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:		Low		Moderate	<input checked="" type="checkbox"/>	High
Vibration:	<input checked="" type="checkbox"/>	Low		Moderate		High
Air Movement:	<input checked="" type="checkbox"/>	Low		Moderate		High
Ventilation:	<input checked="" type="checkbox"/>	Low		Moderate		High
Accessibility:		Low		Moderate	<input checked="" type="checkbox"/>	High

**Overall potential rating:**

Low X Moderate High

Inspectors Signature: 

Date: 7/26/16

Inspectors Name: Jordan Mederer

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 5, 6      Description: Roof Drain Insulation

Material Type:    Surfacing:      Thermal: X      Miscellaneous:

Friable?:       Yes: X       No

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	<u>X</u>	Light		Moderate		Heavy		Unknown	
Water:	None	<u>X</u>	Light		Moderate		Heavy		Unknown	
Physical:	None	<u>X</u>	Light		Moderate		Heavy		Unknown	

**Percent Damaged:** (for inaccessible areas)


Localized:	<u>X</u>	None	0 - 25%	>25%	Unknown
Distributed:	<u>X</u>	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:	<u>X</u>	Low		Moderate		High
Vibration:		Low	<u>X</u>	Moderate		High
Air Movement:	<u>X</u>	Low		Moderate		High
Ventilation:	<u>X</u>	Low		Moderate		High
Accessibility:	<u>X</u>	Low		Moderate		High

**Overall potential rating:**

X     Low     Moderate     High

Inspectors Signature: 

Date: 7/26/16

Inspectors Name: Jordan Mederer

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 8, 9      Description: Drywall Walls/ Ceilings

Material Type:    Surfacing:      Thermal:      Miscellaneous: X

Friable?:       Yes:       No: X

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	<input checked="" type="checkbox"/>	Light		Moderate		Heavy		Unknown	
Water:	None	<input checked="" type="checkbox"/>	Light		Moderate		Heavy		Unknown	
Physical:	None	<input checked="" type="checkbox"/>	Light		Moderate		Heavy		Unknown	

**Percent Damaged:** (for inaccessible areas)


Localized:		None	<input checked="" type="checkbox"/>	0 - 25%		>25%		Unknown
Distributed:	<input checked="" type="checkbox"/>	None		0 - 10%		>10%		Unknown

**Potential for Damage:**

Activity:		Low		Moderate	<input checked="" type="checkbox"/>	High
Vibration:		Low	<input checked="" type="checkbox"/>	Moderate		High
Air Movement:	<input checked="" type="checkbox"/>	Low		Moderate		High
Ventilation:	<input checked="" type="checkbox"/>	Low		Moderate		High
Accessibility:		Low		Moderate	<input checked="" type="checkbox"/>	High

**Overall potential rating:**

Low     Moderate     High

Inspectors Signature: 

Date: 7/26/16

Inspectors Name: Jordan Mederer

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 10 Description: Stucco Wall Plaster

Material Type: Surfacing:  Thermal:  Miscellaneous:

Friable?:  Yes:  No:

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>
Water:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>
Physical:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>

**Percent Damaged:** (for inaccessible areas)


Localized:	<input checked="" type="checkbox"/>	None	<input type="checkbox"/>	0 - 25%	<input type="checkbox"/>	>25%	<input type="checkbox"/>	Unknown	<input type="checkbox"/>
Distributed:	<input checked="" type="checkbox"/>	None	<input type="checkbox"/>	0 - 10%	<input type="checkbox"/>	>10%	<input type="checkbox"/>	Unknown	<input type="checkbox"/>

**Potential for Damage:**

Activity:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Vibration:	<input checked="" type="checkbox"/>	Low	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Air Movement:	<input checked="" type="checkbox"/>	Low	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Ventilation:	<input checked="" type="checkbox"/>	Low	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Accessibility:	<input checked="" type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High

**Overall potential rating:**

Low  Moderate  High

Inspectors Signature: 

Date: 7/26/16

Inspectors Name: Jordan Mederer

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 12, 13, 14, 15, 16	Description: Ceiling Tiles
--	----------------------------

Material Type:	Surfacing:	Thermal:	Miscellaneous: X
----------------	------------	----------	------------------

Friable?: Yes: X No

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	X	Light		Moderate		Heavy		Unknown	
Water:	None		Light	X	Moderate		Heavy		Unknown	
Physical:	None		Light	X	Moderate		Heavy		Unknown	

**Percent Damaged:** (for inaccessible areas)

Localized:	None	X	0 - 25%	>25%	Unknown
Distributed:	X	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:		Low	X	Moderate		High
Vibration:		Low	X	Moderate		High
Air Movement:	X	Low		Moderate		High
Ventilation:	X	Low		Moderate		High
Accessibility:		Low	X	Moderate		High

**Overall potential rating:**

	Low	X	Moderate		High
--	-----	---	----------	--	------

Inspectors Signature:

Date: 7/26/16

Inspectors Name: Jordan Mederer

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 18 Description: Carpet Squares

Material Type: Surfacing Thermal: \_\_\_\_\_ Miscellaneous: X

Friable?: Yes:  No: X

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	<u>X</u>	Light		Moderate		Heavy		Unknown	
Water:	None	<u>X</u>	Light		Moderate		Heavy		Unknown	
Physical:	None	<u>X</u>	Light		Moderate		Heavy		Unknown	

**Percent Damaged:** (for inaccessible areas)


Localized:	<u>X</u>	None	0 - 25%	>25%	Unknown
Distributed:	<u>X</u>	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:		Low	<u>X</u>	Moderate		High
Vibration:	<u>X</u>	Low		Moderate		High
Air Movement:	<u>X</u>	Low		Moderate		High
Ventilation:	<u>X</u>	Low		Moderate		High
Accessibility:		Low	<u>X</u>	Moderate		High

**Overall potential rating:**

Low X Moderate  High

Inspectors Signature: 

Date: 7/26/16

Inspectors Name: Jordan Mederer



**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 19 Description: Linoleum

Material Type: Surfacing Thermal:                      Miscellaneous: X

Friable?:                      Yes:                      No: X

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>
Water:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>
Physical:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>

**Percent Damaged:** (for inaccessible areas)

Localized:	<input checked="" type="checkbox"/>	None	0 - 25%	>25%	Unknown
Distributed:	<input checked="" type="checkbox"/>	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Vibration:	<input checked="" type="checkbox"/>	Low	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Air Movement:	<input checked="" type="checkbox"/>	Low	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Ventilation:	<input checked="" type="checkbox"/>	Low	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Accessibility:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High

**Overall potential rating:**

           Low X Moderate            High

Inspectors Signature:  Date: 7/26/16

Inspectors Name: Jordan Mederer

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 20 Description: 18 x 18 floor tile and mastic

Material Type: Surfacing Thermal:                      Miscellaneous: X

Friable?: Yes:                       No: X                      

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	X	Light		Moderate		Heavy		Unknown	
Water:	None	X	Light		Moderate		Heavy		Unknown	
Physical:	None	X	Light		Moderate		Heavy		Unknown	

**Percent Damaged:** (for inaccessible areas)


Localized:	X	None	0 - 25%	>25%	Unknown
Distributed:	X	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:		Low	X	Moderate		High
Vibration:	X	Low		Moderate		High
Air Movement:	X	Low		Moderate		High
Ventilation:	X	Low		Moderate		High
Accessibility:		Low	X	Moderate		High

**Overall potential rating:**

           Low X Moderate            High

Inspectors Signature: 

Date: 7/26/16

Inspectors Name: Jordan Mederer

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 21 Description: Drywall Walls (New Addition)

Material Type: Surfacing Thermal:                      Miscellaneous: X

Friable?: Yes:                       No: X                      

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>
Water:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>
Physical:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>

**Percent Damaged:** (for inaccessible areas)


Localized:	<input checked="" type="checkbox"/>	None	0 - 25%	>25%	Unknown
Distributed:	<input checked="" type="checkbox"/>	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Vibration:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Air Movement:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Ventilation:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Accessibility:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High

**Overall potential rating:**

           Low X Moderate            High

Inspectors Signature: 

Date: 7/26/16

Inspectors Name: Jordan Mederer

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 23 Description: Black Sink Insulation

Material Type: Surfacing Thermal: \_\_\_\_\_ Miscellaneous: X

Friable?:  Yes:  No: X

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	<input checked="" type="checkbox"/>	Light		Moderate		Heavy		Unknown	
Water:	None	<input checked="" type="checkbox"/>	Light		Moderate		Heavy		Unknown	
Physical:	None	<input checked="" type="checkbox"/>	Light		Moderate		Heavy		Unknown	

**Percent Damaged:** (for inaccessible areas)


Localized:	<input checked="" type="checkbox"/>	None	0 - 25%	>25%	Unknown
Distributed:	<input checked="" type="checkbox"/>	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:		Low	<input checked="" type="checkbox"/>	Moderate		High
Vibration:		Low	<input checked="" type="checkbox"/>	Moderate		High
Air Movement:	<input checked="" type="checkbox"/>	Low		Moderate		High
Ventilation:	<input checked="" type="checkbox"/>	Low		Moderate		High
Accessibility:		Low	<input checked="" type="checkbox"/>	Moderate		High

**Overall potential rating:**

Low  Moderate  High

Inspectors Signature: 

Date: 7/26/16

Inspectors Name: Jordan Mederer

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 24 Description: Window Glazing/ Caulking

Material Type: Surfacing Thermal:                      Miscellaneous: X

Friable?: Yes:                       No: X                      

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>
Water:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>
Physical:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>

**Percent Damaged:** (for inaccessible areas)


Localized:	<input checked="" type="checkbox"/>	None	0 - 25%	>25%	Unknown
Distributed:	<input checked="" type="checkbox"/>	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Vibration:	<input checked="" type="checkbox"/>	Low	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Air Movement:	<input checked="" type="checkbox"/>	Low	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Ventilation:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Accessibility:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High

**Overall potential rating:**

           Low X Moderate            High

Inspectors Signature: 

Date: 7/26/16

Inspectors Name: Jordan Mederer

**Cuyahoga Valley Career Center  
3-Year AHERA Re-Inspection  
Assessment Sheet**

School Name: Cuyahoga Valley Career Center

Homogeneous Area #: 25 Description: Vibration Damper

Material Type: Surfacing Thermal:                      Miscellaneous: X

Friable?:                      Yes:                      No: X

**Type of Damage:** (for inaccessible areas)

Deterioration:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>
Water:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>
Physical:	None	<input checked="" type="checkbox"/>	Light	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Heavy	<input type="checkbox"/>	Unknown	<input type="checkbox"/>

**Percent Damaged:** (for inaccessible areas)

Localized:	<input checked="" type="checkbox"/>	None	0 - 25%	>25%	Unknown
Distributed:	<input checked="" type="checkbox"/>	None	0 - 10%	>10%	Unknown

**Potential for Damage:**

Activity:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Vibration:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Air Movement:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Ventilation:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High
Accessibility:	<input type="checkbox"/>	Low	<input checked="" type="checkbox"/>	Moderate	<input type="checkbox"/>	High

**Overall potential rating:**

           Low X Moderate            High

Inspectors Signature:  Date: 7/26/16

Inspectors Name: Jordan Mederer